FEDERAL ON-SCENE COORDINATOR'S REPORT

FOR

CAPITOL ASSAY LABS SITE Baltimore, Maryland

CERCLA REMOVAL ACTION
May 28, 1987 through July 8, 1987



ENVIRONMENTAL PROTECTION AGENCY

TABLE OF CONTENTS

Facts Sheet

Foreword

I. Introduction

A. Nature of the Site/Initial Situation

B. Location of the Site

C; Efforts to Obtain Cleanup by Potential Responsible Parties

II. Roster of Agencies, Organizations and Individuals

A. Organization of the Response B. Glossary of Abbreviations

III. Narrative of Events

IV. Resources Committed

A. Funding B. Chronological Expenditure Log

C. Estimated Total Cost Summary

V. Effectiveness of the Response A. Activities of the Various Agencies

Potential Responsible Parties
 State/Local Agencies

3. Federal Agencies and Special Forces 4. Contractors

B. Disposal Methods and Quantities Removed

VI. Chronology of Events

VII. Problems Encountered and Recommendations

VIII. Appendices A. Location Map/Site Sketches

B. Funding Documentation

C. Site Safety Protocol

D. POLREPs

E. Newspaper Articles

F. Photographic Documentation

G. CERCLA 106 Order

H. Delivery Order and Procurement Request for ERCS Contractor I. Analytical Data

Region III Incident Notification Report

100002

REGION III CERCLA REMOVAL ACTION

FACTS SHEET

SITE:

Capitol Assay Labs Site

SIZE:

Four buildings, approximately 10,000 square feet each

LOCATION:

Whittington Business Center, Baltimore, Maryland

APPROVAL DATE:

May 28, 1987

PROJECT DATES:

May 28, 1987 through July 8, 1987

DESCRIPTION:

The Capitol Assay Labs Site was a precious metals reclaimer located in a small business/industrial park in Baltimore City, Maryland. Capitol Assay Labs had difficulty in meeting its financial obligations and ceased operations in

March of 1987. Hazardous substances at Capitol Assay Labs were discovered accidentally on May 26, 1987 after one of the company's creditors received a court judgement to repossess assets from the facility. The creditors were

accompanied by a representative of the Baltimore County Sheriff's Department and upon the discovery of open drums chemical containers and gas cylinders, contacted Maryland's Office of Environmental Programs/Waste Management

Administration (MDOEP/WMA). After Maryland's MDOEP/WMA of Health and Mental Hygiene had conducted an initial assessment, the EPA Emergency Response Section was contacted for assistance. The OSC activated \$50,000 under the Delegation of Authority (14-1-A, 5/1/85) to perform a chemical

inventory of the buildings and provide site security until the responsible party agreed to take over the cleanup.

HAZARDOUS MATERIALS:

Corrosive liquids, chlorine gas, sulfur dioxide, cyanides and miscellaneous chemicals.

QUARTITIES REMOVED:

N/A - Responsible Party Takeover Robert E. Caron, Lisa Marie Clark

REMOVAL CONTRACTOR:

O.H. Materials, Inc., Findlay, Ohio

N/A - RP Takeover DISPOSAL LOCATION:

PROJECT CEILING:

\$200,000

PROJECT COST:

\$47,067 (estimated)

COMMENTS:

OSC:

The EPA started the cleanup, but after several days of legal discussions involving EPA Enforcement, the RP took

over responsibility to complete the project.

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report

FOREWORD

This report is submitted in accordance with procedures outlined in the National Oil and Hazardous Substances Collution Contingency Plan (NCP). The primary thrust of the Plan is to provide a coordinated Federal response capability at the scene of an unplanned or sudden discharge of oil or hazardous substances that poses a threat to the public health or the environment. In addition, the provisions of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) promote a coordinated Federal, State and local response to mitigate situations at hazardous waste sites which pose an imminent hazard to public health. The Capitol Assay Labs Site presented an imminent hazard to public health which provided a legal basis for Federal response activities. The provisions of the NCP were implemented by the Environmental Protection Agency (EPA) Region III, Philadelphia, Pennsylvania.

Special thanks are extended to the many agencies and groups who participated in this Federal Removal Activity. This well-coordinated team effort on scene enabled a fincly and efficient cleanup which prevented a major environmental incident due to the chemical hazards present on site.

We wish to thank all the persons who contributed to the successful response and commend them on their professional and timely handling of this pollution incident.

Robert E. Caron Senior On-Scene Coordinator U.S. EPA, Region III Philadelphia, Pennsylvania Lisa Marie Clark Junior On-Scene Coordinator U.S. EPA, Region III Philadelphia, Pennsylvania Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report

INTRODUCTION

A. Nature of the Site/Initial Situation

Capitol Assay Laboratories, Ltd. consisted of four buildings and was a precious metals reclaimer that was believed to have operated from 1976 to approximately March of 1987 when it experienced difficulty meeting its financial obligations and ceased operations.

The site was discovered by accident when a collection agency, accompanied by a representative from the Baltimore County Sheriff's Office, went to Capitol Assay to seize anything of value to satisfy the creditor's claim against the company. Upon discovery of the chemicals and gas cylinders within each of the four buildings, the Sheriff's Department notified the Maryland Office of Environmental Programs Waste Management Administration (MDOEP/WMA). The MDOEP/WMA inspected the site on May 26, 1987 and observed poor housekeeping practices. Many containers of corrosive liquids including some labeled hydrochloric acid, sulfuric acid, nitric acid and hydrofluric acid were located throughout the site. Gas cylinders labeled chlorine and sulfur dioxide were also observed on site. Due to the existing threat of fire and/or explosion, on May 27, 1987, the MDOEP/WMA contacted the EPA Region III Emergency Response Section (ERS) for assistance.

B. Site Location

The Capitol Assay Labs Site was located in a small business/industrial park at 2901 Whittington Avenue in Baltimore City, Maryland. The facility consisted of four buildings (2901-A, 2901-B, 2903-F, and 2903-G) that were leased from the Maryland Industrial Enterprise Development Company.

The site was located less than 1/2 mile from the nearest residential homes (not far from the intersection of Washington Boulevard and Patapaco Avenue) and approximately one mile from the nearest waterway (Gaynn Falls) which flowed directly into the Patapaco River.

Site sketches and a location map are presented in Appendix A of this report.

100005

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report INTRODUCTION (continued)

C. Efforts to Obtain Cleanup by Potential Responsible Parties

After the initial assessment, the OSC activated the \$50,000 Delegation of Authority (14-1-A, 5/1/85) to provide site security until the owner of the property could be located. Once in contact with Jack Meehan (President and owner of Capitol Assay Laboratories, Ltd.), the OSC advised him of his potential liability for cleanup costs should the EPA take action at this site. The owner agreed to take responsibility for the cleanup of the property working under the direction of EPA Enforcement.

At the time of this writing cleanup operations are continuing and are being monitored by EPA Enforcement.

ſĬ

ROSTER OF AGENCIES, ORGANIZATIONS AND INDIVIDUALS, Capitol Assay Labs Site, Baltimore, MD	NDIVIDUALS, Capitol	Assay Labs Site, Baltimore, MD
AGENCY	CONTACT	BRIEF DESCRIPTON OF DUTIES
U.S. Environmental Protection Agency Emergency Response Section 84! Chestnut Building Philadelphia, PA 19107 (215) 597-8907	Robert E. Caron Lisa Marie Clark	Sr. On-Scene Coordinator; responsible for the overall success of the project. Jr. OSC; assisted OSC during site activities.
U.S. Environmental Protection Agency Enforcement Branch 841 Chestnut Building Philadelphia, PA 19107 (215) 597-9800	Richard Dulcey	Issued bilateral consent agreement and monitored RP cleanup.
U.S. Environmental Protection Agency Office of Public Affairs 841 Chestnut Building Philadelphia, PA 19107 (215) 597-9800	Nanci Sinclair	Goordinated press releases, addressed media and residential concerns.
U.S. Environmental Protection Agency Office of Criminal Investigation 84! Chestnut Building Philadelphia, PA 19107 (215) 597-9800	Phil Andrews, Criminal Investigator	Performed criminal investigation using files obtained from the facility.
U.S. Coast Guard Narine Safety Office 40 S. Gay Street Baltimore, MD 21220 (301) 962-5112	Mike Geldmacher	Assisted with the initial site assessment, offered the use of the USCG mobile command post during EPA's assessment.
Agency for Toxic Substances Disease Registry (ATSDR) 841 Chestnut Building Philadelphia, PA 19107 (215) 597-9800	Joyce McCurdy	Certified that the Capitol file boxes were not contaminated and were safe to handle.

i //


State of Haryland Department of Health & Mental Hygiene Office of Environmental Programs Haste Management Administration State of Haryland Department of Health & Mental Hygiene Haste Management Administration State of Haryland Department of Health & Mental Hygiene Office of Environmental Programs Haste Management Administration State of Haryland Department of Health & Mental Hygiene Office of Environmental Programs Haste of Haryland Department of Health & Mental Hygiene Office of Environmental Programs Haste of Haryland Department of Health & Mental Hygiene Office of Environmental Programs Hansoor Zakia Dublic Health Engineer Peggy Powell Ray Feldman Peggy Powell Ray Feldman Baltimore County Sheriff's Department Office of Industrial Hygiene Bultimore County Fire Department State Enforcement Hilliams Ontacted by State to assist in determining Derek Williams Contacted by State to assist in determining Powell Health threats. Contacted by State to assist in determining Derek Williams Contacted by State to assist in determining Powell Health threats. Baltimore County Fire Department State Chief Buzz Melton Haz Mat Chief Haz Mat Chief Hark Cox State OSC; involved with the initial site State OSC; involved with the initi	1	l+					11
ney	Baltimore County Fire Department 1908 Holland Street Baltimore, MD 21223 (301) 396-0178	Baltimore County Health Department Bureau of Industrial Hygiene 303 E. Fayette Street, 4th Floor Baltimore, MD 21202	Baltimore County Sheriff's Department Courts Building 401 Bosley Avenue Towson, MD 21204 (301) 494-3151	Baltimore, MD 21201 (301) 225-5731	State of Maryland Department of Health & Mental Hygiene Office of Environmental Programs Waste Management Administration 201 West Preston Street	State of Maryland Department of Health & Mental Hygiene Office of Environmental Programs Waste Management Administration 2103 Annapolis Road Baltimore, MD 21230 (301) 659-2950	
BRIEF DESCRIPTON OF DUTIES State OSC; involved with the initial site assessment and offered assistance. Public Health Engineer Public Affairs State Enforcement Discovered threat while accompanying creditors of Capitol Assay through the facility. Contacted by State to assist in determining potential health threats. Fire Chief Haz Wat Chief	Ronald Brown Buzz Melton	Derek Williams Charles Courtney		Bernie Baylog Bill Schmidt	Mansoor Zakia Peggy Powell Ray Feldman	Mark Cox	CONTACT
	Fire Chief Haz Mat Chief	Contacted by State to assist in determining potential health threats.	Discovered threat while accompanying creditors of Capitol Assay through the facility.	State Enforcement	Public Health Engineer Public Affairs	State OSC; involved with the initial site assessment and offered assistance.	BRIEF DESCRIPTON OF DUTIES

AGENCY	CONTACT	BRIEF DESCRIPTON OF DUTIES
Roy E. WESTON, Inc./SPER Division	Patricia Donegan	Technical Assistance Team (TAT); performed
53 Haddonfield Road, Suite 306	Kevin Scott	graphic and site activities documentation,
Cherry Hill, NJ 08002	Lynn Wilder	performed contractor monitoring, air
(609) 482-0222	Dave Bute	monitoring, soil sample planning and implementation.
O.H. Materials, Inc.	John Bourret	ERCS prime contractor; provided site
P.O. Box 551		security and provided chemists needed to
Findlay, OH 45839		perform inventory of facility.
(800) 537-9540		
A & S Environmental Testing, Inc.	Craig Achenbach	Performed soil and water analysis.
P.O. Box 130	Stephen Stupp	•
Temple, PA 19560)i
(215) 926-6602		,

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report ROSTER OF AGENCIES, ORGANIZATIONS AND INDIVIDUALS (continued)

A. Organization of the Response

B



Capitol Assay Labs Site
Baltimore, Maryland
Federal OSC Report
ROSTER OF AGENCIES, ORGANIZATIONS AND INDIVIDUALS (continued)

B. Glossary of Abbreviations

1.	BCFD	Baltimore County Fire Department
2.	BCHD	Baltimore County Health Department
3.	EPA	U.S. Environmental Protection Agency
4.	ERCS/OHM	Emergency Response Cleanup Services/O.H. Materials, Inc
5.	ERS	U.S. EPA, Emergency Response Section
6.	MDOEP/WMA	Maryland Office of Environmental Programs/ Waste Management Administration
7.	OPA	U.S. EPA, Office of Public Affairs
8.	osc	U.S. EPA, Federal On-Scene Coordinator
9.	PRP	Potential Responsible Party
10.	RP	Responsible Party
11.	TAT	Roy F. WESTON, Inc., Technical Assistance Team
12.	USCG/MSO	U.S. Coast Guard/Marine Sarety Office

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report

NARRATIVE OF EVENTS

The Capitol Assay Labs Site was what appeared to be an abandoned metal plating and reclaiming facility in a mixed business/industrial park located in Baltimore City, Maryland.

The site was discovered by accident when a creditor attempted to repossess assets in order to satisfy a claim against the company. The creditor was accompanied by a representative of the Baltimore County Sheriff's Department, who notified Maryland's Office of Environmental Programs, Waste Management Administration (MDOEP/WMA) of the potential threat that existed at the facility due to the presence of cylinders and chemical containers.

On May 26, 1987 personnel from MDOEP/WMA performed an initial assessment of the facility and found many open drums of corrosive liquids, chemical containers and gas cylinders. The State of Maryland contacted the EPA Region III Regional Response Center (RRC) in Philadelphia requesting emergency response assistance. OSCs Robert E. Caron and Lisa Marie Clark responded with members of TAT to the site where they met with representatives of both the State and USCG. A Level "B" entry (see Appendix F, Photo #2) was made inside the buildings which revealed several hundred open drums posing a fire and/or explosion threat and chemical containers stored in extremely incompatible situations throughout the office, laboratory, and warehouse areas.

The following morning the OSC contacted Jack Meehan (President and owner of Capitol Assay Labs) and informed him of his potential liability for cleanup costs should EPA become involved with the cleanup of this site. Mr. Meehan informed the OSC that he would assume the responsibility of the cleanup, but that he would like to first contact his attorney. After speaking with Mr. Meehan, the OSC used his Delegation of Authority (14-1-A, 5/1/85) to activate \$50,000 to provide site security and begin a chemical inventory of the four buildings. The OSC also spoke with a Mr. Dave Cohen, the chemist at Capitol

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report NARRATIVE OF EVENTS (continued)

Assay Labs who provided a partial inventory of the chemicals contained in the buildings. Mr. Cohen also agreed to assist with the cleanup at the site, but the OSC informed him that the cleanup contractor would have to conform with OSHA regulations and that employees of the lab were not qualified to perform the cleanup. Later that evening, the owner/landlord of the property (Bob Mecker) arrived on site and agreed to take partial responsibility for cleanup operations.

A bilateral consent agreement was drawn up by EPA Enforcement that provided the responsible party with guidance in the cleanup procedures. A local cleanup contractor (EnPro) was hired by the RP and cleanup operations proceeded under the direction of EPA Enforcement.

RESOURCES COMMITTED

A. Funding

On May 28, 1987, Special Bulletin A was submitted regarding the use of and need for an emergency activation of \$50,000 under the OSC's Delegation of Authority, 14-1-A (5/1/85). A copy of Special Bulletin A is included as Appendix B of this report.

An additional funding request in the amount of \$150,000 was approved on June 4, 1987 bringing the project ceiling to \$200,000. A copy of the additional funding request is also located in Appendix B of this report.

B. Chronological Expenditure Log

Date 1987	EXTRA ERCS	MURAL TAT	INTRAMURAL EPA	Total Cost to Date	Ceiling
05/28	\$ 2,051.28	\$ 2,275.50	\$ 1,309.75	\$ 5,636.53	\$ 50,000
05/29	5,072.98	2,275.50	1,309.75	14,294,76	
05/30	5,560.89	2,275.50	1,309.75	23,440.90	
05/31	1.882.32	2,275.50	1,309.75	28,908,47	
06/03	-			28,908,47	\$200,000
06/10	6,998.40		-	35,906.87	
06/19	2,087.64	,	Pin Pin	37,994.51	
07/06	9,072.00			47,066.51	-
	\$32,725.51	\$ 9,102.00	\$ 5,239.00	\$47,066.51	\$200,000

C. Total Cost Summary (Estimated)

1. Extramural

l.	Extramural	
	ERCS	\$32,725.51
	Personnel/Labor	• •
	Equipment	
	Materials	
	Subcontractors	
	a) Analytical	
	b) Transportation	: 43
	c) Disposal	•
	d) Miscellaneous	
	TAT	9,102.00
	Extramural Subtotal	\$41,827.51
2.	Intramural	
	EPA	\$ 5,239.00
Tot	tal Estimated Project Cost	\$47,066.51

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report

EFFECTIVENESS OF THE RESPONSE

A. Activities of the Various Agencies

1. Potential Responsible Parties

The responsible party (RP) accepted responsibility for the cleanup of the site after being notified by the EPA that a potential health threat existed at the facility. Initially, there was some delay on the part of the RP due to legal matters involving the EPA and RP. Eventually a cleanup contractor was located and cleanup operations were started. The cleanup proceeded under the direction of EPA Enforcement.

2. State and Local Forces

Personnel from the Baltimore County Sheriff's Office were the first to discover the chemical hazards on site and reported their findings to the MDOEP/WMA.

The MDOEP/WMA performed an initial assessment, realized the potential health threat posed by the site, and contacted security personnel to restrict access to the buildings. State personnel later requested assistance from the EPA Region III Emergency Response Section.

The Baltimore County Fire Department (BCFD) provided fire units and fire fighters during the assessment and remained on standby during the EPA chemical inventory. Fortunately, the services of the BCFD were not required.

3. Federal Agencies and Special Forces

Robert E. Caron served as the Federal On-Scene Coordinator (OSC) during the emergency response and subsequent assessment and was assisted by Jr. OSC Lisa Marie Clark. The OSCs were responsible for coordinating participants involved to ensure the completion of a proper cleanup action.

The Agency for Toxic Substances Disease Registry (ATSDR) reviewed wipe sample results taken from Capitol Assay Labs' files and certified they were safe to handle and not contaminated.

Capitol Assay Labs Site
Baltimore, Maryland
Federal OSC Report
EFFECTIVENESS OF THE RESPONSE (continued)

A. Activities of the Various Agencies

3. Federal Agencies and Special Forces (continued)

EPA Enforcement was responsible for developing the bilateral consent agreement (106 Order) that provided the guidelines under which the responsible party was to proceed with the cleanup.

The . \ Office of Public Affairs (OPA) was responsible for issuing press releases to ensure accurate media coverage and to address concerns expressed by area residents.

The United States Coast Guard/Marine Safety Office (USCG/MSO) provided the use of a mobile command post during the assessment.

4. Contractors

The Spill Prevention and Emergency Response Division of Roy F. WESTON, Inc. provided personnel from the TAT to provide support to the OSC as follows:

- 1. Soil sample planning and implementation,
- 2. photographic documentation of site activities,
- air monitoring,
 contractor monitoring,
- 5. site activities documentation,
- 6. coordination of laboratories, and
- QA/QC of analytical results.

O.H. Materials, Inc. of Findlay, Ohio, was the ERCS prime contractor during the emergency response and provided the manpower and equipment necessary to perform the following:

- 1. Chemical inventory,
- 2. container sampling,
- 3. sampling analysis, and
- 4. site security.

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report EFFECTIVENESS OF THE RESPONSE (continued)

B. Disposal Methods and Quantities Removed

The RP party assumed all responsibility for the cleanup; and, there- fore, the disposal methods and quantities removed were not monitored by the EPA Emergency Response Section.

11

In addition, the RP continues cleanup activities under advice and guidance of EPA Enforcement making disposal methods and quantities removed unavailable at the time of this writing.

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report

CHRONOLOGY OF EVENTS

This section presents a brief summary of events as they occurred during the Capitol Assay Labs Site in an effort to provide the reader with an overview of site activities.

- O5/26/87 MDOEP/WMA performed an assessment at the Capitol Assay Laboratories, Ltd. after being notified by the Baltimore County Sheriff's Office of the potential threat that existed at the facility. (The Sheriff's Department had discovered the chemicals while accompanying a creditor who was trying to recover assets to satisfy a claim against the owner/President, John Meehan). The State of Maryland provided security personnel at the facility until such time as additional assistance could be obtained.
- O5/27/87 The EPA Region III Regional Response Center (RRC) received the report regarding Capitol Assay Laboratories from the State of Maryland. OSCs Robert Caron and Lisa Clark responded with members of TAT and met with State OSC Mark Cox. At 2200 hours, a Level "B" (see Appendix F, Photo #2) entry was made to assess the situation inside the four buildings, which appeared to be abandoned. The assessment within the building revealed hundreds of opened drums and chemical containers in extremely incompatible situations which posed a fire and/or explosion threat throughout the office, laboratory, and warehouse areas.
- O5/28/87 The OSCs, TAT, State and USCG representatives met at USCG/Marine Safety Office (MSO) in Baltimore to discuss a plan of action for the site. The State of Maryland and USCG agreed to having EPA assume the lead on this site. While at the MSO, OSC Caron contacted Mr. Jack Meehan (President and owner of Capitol) and advised him of the potential liability for cleanup costs if EPA took action at this site. Mr. Meehan expressed that he would agree to take responsibility for the cleanup of the site, but that he would first consult his attorney. After issuing verbal notice to the RP, the OSC utilized his Delegation of Authority (14-1-A, 5/1/85) to activate \$50,000 in emergency funding to provide site security and to begin a chemical inventory of the four buildings.

Capitol Assay Labs Site
Baltimore, Maryland
Federal OSC Report
CHRONOLOGY OF EVENTS (continued)

- O5/28/87 EPA, TAT and State personnel returned to the site to await the arrival of the ERCS contractor. Upon ERCS' arrival, a meeting was held with EPA, TAT, State, and David Cohen (Capitol's chemist). Mr. Cohen, who was also being considered as a PRP (potential responsible party), provided background information and details about materials being stored in the buildings. Bob Becker (property owner/landlord) was also advised of his potential liability concerning the site.

 Mr. Becker later arrived on scene and agreed to share responsibility for cleanup.
- O5/29/87 Environmental samples from around the site had been collected by TAT and given to ERCS for analysis. Firearm paraphernalia and ammunition were observed in one of the offices and confiscated by Maryland Enforcement. EPA Enforcement were on scene to discuss a bilateral consent agreement with PRPs. Press conference and television interviews were held with local media by EPA/OPA. Both RPs had a cleanup contractor (J&L Industries) provide an estimate; however, due to the contractor's noncompliance with safety regulations, only a visual assessment could be performed.
- 05/30/87 A partial inventory of buildings A and B had been completed, but due to the depletion of the \$50,000, site activities were placed on hold until an additional funding request could be approved.
- 06/02/87 An additional funding request was prepared and sent through the EPA chain of concurrence.
- 06/02/87 TAT delivered environmental samples to A&S Laboratory.
- 06/04/87 Additional funding request was approved for \$150,000; new ceiling \$200,000. TAT made Level "B" entry with J&L on which to base a cleanup cost estimate. Investigation was started by the EPA Office of Criminal Investigation. EPA Enforcement on scene to gather information about company operations/practices. Around-the-clock (24-hour) site security maintained.
- 06/10/87 A public meeting was held at the Morrell Park Recreation Center.

 The public showed gratitude for EPA's presence and concern.

Capitol Assay Labs Site Baltimore, Maryland Federal OSC Report CHRONOLOGY OF EVENTS (continued)

- O6/11/87 TAT collected wipe samples from file boxes that were retrieved from Capitol and stored at the Office of Criminal Investigation. Samples were shipped to A&S Lab for analysis to confirm that () files were free of contamination and safe to handle.
- O6/27/87 RP agreed to assume responsibility for cleanup. ERCS exceeded their \$30,000 ceiling with the provision of site security to date, awaiting RP decision to assume cleanup responsibility. As a result, funds were redesignated from the original \$50,000 project ceiling to cover the ERCS costs. Project expenditures did not exceed the \$50,000 Delegation of Authority activation.
- O7/08/87

 EPA Program Elements were successful in obtaining a commitment from the RP to take over the cleanup. RP continued under the direction of EPA Enforcement. Wipe samples collected by TAT from the Capitol file boxes showed no significant contamination after review by ATSDR. EPA/ERS_involvement was concluded.
- 08/26/87 EnPro of Baltimore was hired by RP as cleanup contractor for the duration of cleanup activity.

Çapitol Assay Labs Site Baltimore, Maryland Federal OSC Report

PROBLEMS ENCOUNTERED AND RECOMMENDATIONS

overall, the combined efforts of the various participating organizations/
agencies participating in the Capitol Assay Labs Site enabled emergency
response activities to proceed in an efficient and timely manner. There were
minor delays regarding the responsible party takeover, but once EPA Enforcement
became involved in the cleanup, RP activities continued smoothly.

At the time of this writing, the RP continues cleanup actions monitored by EPA Enforcement.




BALTIMORE CAPITOL ASSAY LABS
BALTIMORE MARYLAND


EMERGENCY RESPONSE

SITE SKETCH

Capital Assay Laboratories, Ltd. Baltimore, Maryland 1)



Capital Assay Laboratories, Ltd. Baltimore, Maryland



100024

NOT TO SCALE

11

SHEET..... SAMPLE TASK NO. APPROVED BY METHOD REV. BY . DEPT 4 DRUM STORAGE Fill Dirt Area ENTRY 100025

ENGINEERING OHM COMPUTATION SHEET TITLE OF PROJ. OR STUDY CAPITAL ASSAY LAKORATORIES LTD. DATE 10 11 12 13 14 15 16 17 18 19 20 21 22 23 ROOM A (I) (B) 3 0 0 0 0 **99999** KIL 23

UPK STANDARDS FOR MINIMUM ESSENTIAL INSTALLATIONS

UDJECT	r	<u> </u>		,	·							:				WOR	K#_				
	2 3	4 5	4 7		-	10 1	1 12		PUTER 14		4 17	1.8	10		ATK_ 11 22	23	24	25 2	26 2		9
	; , ,					~				,				,			Ī				
											,	٠	•								
		•			!	Roo	120	12									;	•			
						1 100		ט						• • •	• •	•		•		••	
												,		:			:				
																	:				
		100				Œ) R) A	P	D.A.	00	6		<u>, </u>	A	<u> </u>	+				1
		3		Ø	ı			<i>5</i>	60	90	8	6	B	(8	8	9		63		•
		8			6	<u>) </u>	1		0)		. ,		4		•	É		77	•	
		0		0	6	90) .	1714 MG	-G)				ļ					<i>"</i> }~∵	~~ ~ • •	
		I .		a		0	<i>(</i> a)		G	3)	•			1	•	γ ₂		d)		
		6		8	•		0	10	F						V		1	(7)			
		3	"	(9))	٠		٠	•	, :		*****	. 1-4						· 1 · «*****		
		6	32	Y		٠.			,. .	•				!							
		1	2	. :		٠.	į		•	٠ .		•	•						٠,	_	_
		69					į			: 									D1 b1 4.4		
		(19	y	i	•				.		• •				• •	١.	;				
		600	72)(1	A	• ;	• • •		•		1				į,		. 5		;, ·	: :		
- 5. - • • •			<u>``</u>						, 4: m 1: .			.,		· · · · · ·		. G	<u>ي'</u>	<u> </u>	3	FG	
		1 '			• • •				1.	;	ri e	٠	•	1		13		:	•		
			٠	Ì		٠.			., 2			÷		.` 	ر ھ	भि	ď	79 –	138	. :	. :
			f	. [•.			Q	497		3 4	an i	LAC		
		بند ا			i.				·•• [··), :			1	53		(F		٥٠	3	וט	
		168	:		<u>.</u> }.		Ì	+	, -	٠	63)			(S				! . :		
		63		16	Ð	(165			62	رها	•••	j .	-				B) .	٠	
•		703	S	Ī	. • *			•	-			1	<u>6</u>	ß	9	S		!	•	···	
		k .	K						4	,	1;	(Ó	1s) (E		CS	Ś			
		1.5)) }					٠:		.]		:	4		٠, ١			ວິດ ກິດຕິ	i o i	,	

R

SPECIAL BULLETIN A Capitol Assay Labs Site Whittington Avenue Baltimore, Maryland

Date: May 28, 1987

FROM: Robert E. Caron

On-Scene Coordinator

THRU: Stephen Wassersug, Director

Hazardous Waste Management Division

THRU: Thomas Voltaggio, Chief

Superfund Branch

THRU: Thomas Massey, Chief

Emergency Response Section

I. INTRODUCTION

A preliminary assessment performed by the EPA Emergency Response Section and the Technical Assistance Team in accordance with the NCP has identified a potential risk of harm to human health and the environment posed by the presence of open and leaking hazardous substances which may present a substantial risk of harm to public health or welfare.

The Delegation of Authority 14-1-A (5/1/85) authorizes the OSC to approve CERCLA removals with a total cost of less than \$50,000. Therefore, the OSC has approved the use of CERCLA funds at this site for control of site access and completion of an inventory of hazardous substances on site.

II. BACKGROUND

The Capitol Assay Labs Site consists of four buildings on Whittington Avenue in Baltimore, which until nine weeks ago had been fully operating as a precious metal reclaiming facility. The buildings on site consist of an office, laboratory, and two storage areas, all of which contain hazardous substances including but not limited to the following (as per labelling and employee information): perchloric acid, hydrochloric acid, nitric acid, sulfuric acid, cyanide (in dry and liquid form), monohydrazine sulfate and elemental mercury.

In the recent past, unsupervised entry throughout the buildings had been taking place, as creditors of the company owner, J. Meehan, were considering removing unsecured chemicals as recoverable assets. An inspection of the facility by the

Baltimore sheriff led to an assessment of the facility by the Maryland State Department of Health and Mental Hygiene on May 26, 1987, at which time the situation warranted notification of the EPA Response Center for emergency assistance on May 27, 1987.

An emergency assessment of the property by EPA on that date revealed several hundred acid drums in various condition throughout the facility, stacked floor to ceiling in some areas, along with 500-600 smaller chemical containers and bags, and several cylinders (chlorine, acetylene) which appeared secure at the time of inspection. Conditions of extreme incompatibility exist between improperly stored acid containers, cyanides, elemental mercury, and monohydrazine sulfate.

The potential for hazardous release of chemicals through fire and accidental chemical reactions due to improper story was observed by the EPA during the emergency assessment, and corroberated by state and local hazmat forces on scene.

III. THREAT

The threat of direct human contact with hazardous substances on site is substantial. Access to the site by creditors had been temporarily restricted by the state by installing site security personnel. However, the state contribution in this manner cannot continue indefinitely and will not prevent accidental fire or chemical reaction, and the resultant hazardous vapor releases.

IV. SCOPE OF WORK

The scope of work proposed for implementation with the emergency \$50K funding will include assuming restriction for site access, performing a complete site inventory, and taking environmental samples on the property to determine tht extent of contamination outside the facility.

The proposed budget is as follows:

ERCS - \$30K TAT - \$10K EPA - \$10K

V. OSC ACTION

Because the conditions at the Capitol Assay Lab Site meet the NCP Section 300.65 criteria for an immediate removal action, I have approved this action. The estimated total project cost is less than \$50,000.

Robert E. Caron, OSC U.S. EPA, Region III Philadelphia, PA

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION III

841 Chestnut Building Philadelphia, Pennsylvania 19107

SUBJECT:

Request for Additional Funding for the Capitol Assay

Lab Site in Baltimore City, Baltimore County, MD

FROM:

Robert E. Caron, Sr. On-Scene Coordinator Lisa Marie Clark, Jr. On-Scene Coordinator Emergency Response Section (3HW22)

TO:

James M. Seif

Regional Administrator (3RA00)

THRU:

Stephen R. Wassersug, Director Hazardous Waste Management Division (3HWOC)

PURPOSE

A preliminary assessment, performed in accordance with the National Contingency Plan, has identified a potential risk of harm to human health and the environment presented by the Capitol Assay Lab Site in Baltimore City, Baltimore County, Maryland. , Emergency funds in the amount of \$50,000 were activated by the OSC during the emergency response on May 27, 1987. At this time, Region III is requesting additional funds in the amount of \$150,000, which includes 15% EPA HQ. Of the funds requested, \$50K will be used to complete the assessment and the remaining \$100K will be used to begin cleanup action at the site.

II. BACKGROUND

The Capitol Assay Labs Site consists of four buildings on Whittington Avenue in Baltimore, which until nine weeks ago had been fully operating as a precious metal reclaiming facility. The buildings on site consist of an office, laboratory, and two storage areas, all of which contain hazardous substances including but not limited to the following (as per labelling and employee information): perchloric acid, hydrochloric acid, nitric acid, sulfuric acid, cyanide (in dry and liquid form), monohydrazine sulfate and elemental mercury.

In the recent past, unsupervised entry throughout the buildings had taken place, as creditors of the company owner, J. Meehan, were considering removing unsecured chemicals as recoverable assets. An inspection of the facility by the Baltimore sheriff led to an assessment of the facility by the Maryland State Department of Health and Mental Hygiene on May 26, 1987, at which time the situation warranted notification of the EPA Response Center for emergency assistance on May 27,1987. An emergency assessment of the property by EPA on that date revealed several hundred acid drums in various conditions throughout the facility, stacked floor to ceiling in some areas, along with 500-600 smaller chemical containers and bags, and several cylinders (chlorine, acetylene) which appeared secure at the time of inspection. Conditions of extreme incompatibility exist between improperly stored acid containers, cyanides, elemental mercury, and monohydrazine sulfate.

The potential for hazardous release of chemicals through fire and accidental chemical reactions due to improper storage was observed by the EPA during the emergency assessment, and corroberated by state and local hazmat forces on scene.

111. ACTIONS TAKEN TO DATE

On May 27, 1987, EPA immediately responded to a request for assistance from the MDWMA regarding a potentially hazardous situation presented by an abandoned metal plating and reclaiming facility in the city of Baltimore, Maryland. EPA, MDWMA, and TAT entered the four buildings used by the facility. The entry revealed hundreds of open drums and chemical containers in extremely incompatible situations throughout the office, laboratory, and warehouse areas. At that time, the OSC determined that a potential threat to human health and the environment existed at the site and authorized the use of CERCLA (\$50,000) Emergency Funding to provide site security and perform a chemical/container inventory of the facility. Access to the facility was restricted on May 27, 1987. No Responsible Party assumed at that time.

According to State officials, continuation of this response was beyond the capabilities of the State of Maryland. The OSC coordinated the response with the USCG (MSO Baltimore) as per the memorandum of understanding regarding emergency response activities in this jurisdiction; all State, Local, and Federal forces on scene concurred with EPA's decision to continue with the response.

On May 28, 1987, ERCS was activated to begin the chemical inventory process. Before the \$50,000 funds were depleted, 321 containers were inventoried inside Building "A". Environmental samples (soil and water) were taken of a drainage area behind the facility and are currently being analyzed for priority pollutant metals, volatile organics, base neutrals, and cyanide.

The OSC directed ERCS to maintain 24-hr. site security beginning on May 28, 1986. On May, 29, 1987, EPA, USCG, and MDWMA met with the PRP to discuss clean-up options and continue negotiations for possible PRP takeover of cleanup. Currently, the OSC is awaiting the results of Enforcement's efforts with PRP negotiations.

On May 30, 1987, because costs (analytical included) were approaching the \$50,000 ceiling, the OSC was forced to shut down site operations until additional funding could be acquired. Twenty-four hour security is currently being maintained at the site.

IV. THREAT

The threat of direct human contact with hazardous substances on site is substantial. Access to the site by creditors had been temporarily restricted by the state by installing site security personnel. However, the state contribution in this manner cannot continue indefinitely and will not prevent accidental fire or chemical reaction, and the resultant hazardous vapor releases.

V. ENFORCEMENT

See attachment: Confidential Enforcement Status.

IV. PROPOSED PROJECT AND COSTS

Phase I of this project will include the completion of the inventory within the four buildings forming the facility, and the analysis of all environmental samples taken to determine possible off-site migration of contaminants. Estimated costs for this phase are \$50,000.

Phase II of the project will begin removal/cleanup activities at the facility. This phase is expected to begin in 2 (two) weeks (June 14, 1987). Estimated costs for Phase II are \$100,000.

IV. PROPOSED PROJECT AND COST (continued)

Proposed costs are as follows:

Cleanup Contractor (ERCS) TAT EPA	\$95,500 25,000 7,000
Subtotal	\$127,500
15% EPA HQ	\$ 22,000
Total Estimated Costs	\$150,000

VII. JUSTIFICATION

In order to mitigate the ongoing threat to human health and welfare and the environment, it will be necessary for the EPA to obtain additional funding. Further assistance from any other Federal or State agency will not be forthcoming, and without a funding increase, this site will not be stabilized and secured on a timely basis. This site is not on the National Priorities List (NPL).

VIII. REGIONAL RECOMMENDATION

The conditions at the Capitol Assay Labs Site meet the criteria set forth in the National Contingency Plan Section 300.65 for a removal request. The estimated total removal project costs are \$150,000.

You may indicate your approval or disapproval by signing below.

APPROVE	Janul	le Dis		DATE	JUN 3	- 1987
	J	1				
		•	4.5			
DISAPPROVE				DATE		

HAZARDOUS WASTE SITE INVESTIGATION AND EMERGENCY RESPONSE HEALTH AND SAFETY PLAN

Assignor: Bob CARON REGION III
Date of Inspection: 5/27/\$7 Time: 2/30 TDD No. Original Safety Plan: Yes No Modification No.
site Name: CAPITOL Assay LABS Site
Site Address: Street No. 2901. A Whitington Ava City Baltimore
County Galffase 2ip Code 2/23 U
Site Contact: A. Mark Cox Phone (361) 659-2950
Directions to site: Fear PHILA - 555 into MO. How
WASHINSTON AVE - 40 SONK ON WASH AVE TO POTOSED AVE AR.
Kap Attached: Yes No No.
If Remote Location: Latitude Longitude
SITE HISTORY: Plecials make sociation . Craditors award money
Belt. Sherills ged involved - who controled ma wmg - poor house to
INCIDENT DESCRIPTION
TYPE: A) Spill Air Release Fire MW Site Other
B) Assessment X Sampling Emergency Response Clean-up/Removal Other (specify)
C) Urban/Residential Commercial Industrial Rural Remote
PHYSICAL DESCRIPTION
Size of Site: ~ 2 acre Terrain: flat Weather clear
Containers Involved in the Release or Incident
Drums / No 100035
Truck License No. Tanker Box 100035
Railroad Car Tank No Box No
SpillSourceApproximate Volume
Other /
OCRET

			· ·	
MATERIALS INVOLVE	:D:			,
Nama	TLV	IOLH	Overexposu	re Symptoms
Ni fric Acid		ره ۱۵۵	Irrit eye	s mec. n.a.h.
Julpavic Acco			**************************************	7
Chlorine			11 00 115 1 10	. V
Cretorino	~~~~~~~	1000	e 11 eeps nos	a along
· · · · · · · · · · · · · · · · · · ·			······	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		 	
SPECIAL HAZARDS:_	Hard H	Hots sho	uldbe won	20
		,		
anticipated level	OF PROTE	CTTON /clr	cle one): A B	CD
WHY: unknowns.			. , 🔾	, , ,
WARE: CON PRICEDO	PG251 (2).	a (Remio	a jacrios	
				
FIRST AID INSTRUC	TIONS FOR	R KNOWN CON	TANINANTS: Fr.	tente umach
PERSONNEL EXPOSUR	- WASABO		V-adazata In	les Messigness
				Radioactive U
Biological L	_ Fire_	H Explor	ion Unknow	m_H
PERSONNEL PHYSICA	L SAFETY	HAZARDS:	ï	•
Heat Col	.d N	oise	Inderground Util	ities
Overhead Util	ities	_ Heavy E	quipment \$1	ip, Trip, Fall
			Airlines Cy	
•				-Wall, Floor_
			ds, Lagoons 1/	/
mrdaras IU ol	en Conca	LHEES, FOR	ma' medantia	1)
م. م				100036

ACTIONS TAKEN ON S	TE:
vas Entry Made: Y	ES WO
Equipment Used: (circle) LEVEL A & C D WHY: Ilaknowns -
Acids	culiader
600)	DD Wadel Carb Com Three
•	PR Kodel Cart./Can. Type
	oly Tyvek Acid Suit
	Cotton Coveralls
	Butyl Nitrile Viton Other
Foot Gear: Saf	ety Boots Outer Boots Booties Other Hip
Description of Dec	contamination Used: Dry Decar
AIR MONITORING	Performed by: TAT 5.Ph
	s: Radiation Meter DO CGI NO
1.	OVA ENU N/O Detector Tube N/O
Winds Speed	Other
	Direction Temp. Rel. Run. B.P.
ام والمنامس ()	storing Data No According Chlorine and
- U Sharlet	he marte after secheelching retail for
Sampling	Performed by:
Sampling Plan (Y	or N) / If yes attach copy to safety plan
No. of Samples: (SolidLiquid Gas Other
,	
	fied of Potential Hazard Level? Yes No
Analyses:	q = q
	100034
nambered Commence	·

	1 2 1 2
DOCUMENTATION	Performed by: THIM 5-06 But Donega
Type: Photo	Log Book Recorder Video
PUBLIC IMPACT	
Distance to Nearest:	Residence < School < 1 A Hospital 1 M
	Public Building < 100 yds other.
Evacuation: Yes	No Number By Whom:
ENVIRONMENTAL IMPACT	
Nearest Waterway	: Gwynns Falls Distance: / mi
Condition	Observed Potential None
Surface Water Contami Ground Water Contami Drinking Water Contami Air Contamination Soil Contamination Stressed Vegetation Dead Fish, Other Ani	ination nation ination
	(NAME, AGENCY, PHONE, ON OF OFF SITE)
SITE MANAGER:	TOR: DAVE BUKE
EPA	Have Read & Understood The Site Safety Plan (check)
TAT E. S.c. H. Dove Rude Lynn 13:1	de la
STATE	100038
OTHER ALONGE	C. Jackson

1)

EMERGENCY INFORMATION

EMERGE	Jamy	Fire Police plance	Location Bulk Off Bulk City St. Acous		hone 4((1)(4()	Notifie	Y Y q (X/N)
DIRECTIONS (ATTACE	TO HOSPIT	<u>√</u> L:	<u> </u>	map			
ADDITIONAL	. EMERGENCY	PHONE CON	PACTS:			•	
NATIONAL 1 WESTON MEI WESTON 24 PESTICIDE EPA ERT EI RCRA HOTIL	ALCOHOL, T RESPONSE CE DICAL EMERG HOUR HOTLI INFORMATIO MERGENCY	obacco & F http: ency servi he n service	CB	(800) (Day) (800) (800) (513) (513) (215) (800) (800)	124-9300 424-906 (404) 1 124-9555, 124-8802 121-3063 524-1925, 145-7633 121-6660 424-9346 835-9500	29-2868 (202)	(Night)
Dwanawad 1	me Valle	: : 50.4	'/ '	,	Date:	-1-0	100 6
Paulauad 1	by: <u>Keni</u> l	1	4		D464;	12100	/ ¥ / _ ' '
Approved	*					0/1/6	
SPER HSO	Reviewed 1	erformed:	Yes	No	Date:		
•	.,						
O);	W			įI		100039

TLX II RECV CONNECTED 28-May-87 12:22 43

EPAOHM PHA

WU INFOMASTER 4-0123478148-001 05/28/87 ICS IPMMTZZ CSP 3019625115 DGM TDMT UG BALTIMORE MD 660 TWX 7106700716 EPADHM PHA **EMERGENCY RESPONSE**

05-28 1124A EST

POLREP I

4218 EPA PHA

CAPITOL ASSAY LABS SITE WHITTINGTON AVE BALTIMORE MD I. SITUATION (1200 HOURS 5-28-87)

A. AT 2000 HOURS 5-27-87, EPA AND TAT RESPONDED TO A REQUEST FOR ASSISTANCE FROM THE MARYLAND DEPARTMENT OF HEALTH AND MENTAL HYGENE ARDING A POTENTIALLY HAZARDOUS SITUATION PRESENTED BY AN ABANDONED METAL PLATING AND RECLAIMING FACILITY IN THE CITY OF BALTIMORE AND INITIAL ENTRY AND ASSESSMENT OF A FACILITY REVEALED HUNDREDS OF OPEN DRUMS AND CHEMICAL CONTAINERS IN EXTREMELY INCOMPATIBLE SITUATIONS THROUGHOUT THE OFFICE, LABORATORY, AND WAREHOUSE AREAS. DUE TO THE

POTENTIAL THREAT TO HUMAN HEALTH AND THE ENVIRONMENT PRESENTED BY THE POTENTIAL FOR FIRE AND EXPLOSION INVOLVING HAZARDOUS CHEMICALS AT THIS

SITE, THE OSC (CARON) HAS ACTIVATED THE 50 K EMERGENCY FUNDING TO PROVIDE SITE SECURITY AND COMPLETE THE CHEMICAL INVENTORY. ACCORDING TO STATE OFFICIALS, CONTINUATION OF THIS RESPONSE IS BEYOND THE CAPABITILTIES OF THE STATE OF MARYLAND. NO RESPONSIBLE PARTY HAS ASSUMED

RESPONSIBILITY FOR THE SITE AT THIS TIME. THE OSC HAB COORDINATED THE RESPONSE WITH USCG DF (MSO) BALTIMORE) AS PER THE MEMORANDUM OF

UNDERSTANDING REGARDING EMERGENCY RESPONSE ACTIVITIES IN THIS JURISDICTION; ALL STATE, LOCAL AND FEDERAL FORCES ON SCENE CONCUR WITH EPA DECISION TO CONTINUE WITH RESPONSE.

B. PERSONNEL ON SCENE 5-27-87: EPA-2 USCG-1 MDDEP/NMA-4 SECURITY-2 AND BALTIMORE CITY FIRE DEPARTMENT-1 //

C. WEATHER- CLEAR WARM HIGH 70'S. II. ACTIONS TAKEN

A. EPA RECEIVED VERBAL NOTIFICATION FROM THE MONMA AT APPROXIMATELY 1510 HOURS 5-27-87 REGARDING THE CAPITAL ASSAY LABS, AKA CAL LTD., AN ABANDONED PRECIOUS METAL RECLAIMING FACILITY IN A RESIDENTIAL/LIGHT INDUSTRIAL AREA OF BALTIMORE. STATES REQUESTED EPA ASSISTANCE IN ASSESSING POTENTIAL HAZARDS PRESENTED BY THE SITE DUE TO LIMITED STATE

CAPABILITY. EPA TAT TO RESPOND AT 1600 HOURS 5-27-87. TAT ON SITE AT STATE OFFICES AT 1900 HOURS THAT DATE TO OBTAIN BRIEFING FOR OSC'S CARON AND CLARK MHO ARRIVED ON BITE SHORTLY THEREAFTER. EPA TAT AND STATE (CDX) ON SITE 1955 HOURS. ADDITIONAL PERSONNEL ON SITE INCLUDED MODEP SCHMIDT, ZABAI, AND BALDG, USCG GELDMACHER; FIRE DEPARTMENT REP CHARA; AND SITE

PERSONNEL HIRED PREVIOUSLY BY STATE.

C. EPA/TAT/STATE PERFORMED LEVEL B ENTRIES UNTIL 2300 HOURS 5-27-87 TO ASSESS HAZARD POTENTIAL OF SITE. SITE CONSISTS OF FOUR BUILDINGS:

OFFICE, LABORATORY, AND TWO STORAGE AREAS. HUNDREDS OF DRUMS, CONTAINERS AND REAGENT BOTTLES ARE PRESENT THROUGHOUT ALL AREAS OF THE FACILITY AND ARE STACKED FLOOR TO CEILING IN SOME AREAS. THE MAJORITY OF CONTAINERS AND DRUMS ARE UNLABELED CYLINDERS OF CHLORINE GAS AND ACETYLENE PRESENT; APPEAR SECURE AT THIS TIME. DRUMS LABELED AS HAZARDOUS WASTE HAVE BEEN FOUND ON SITE. STATE INVENTORY PERFORMED 5-26-87 REVEALED AN ESTIMATED 400-700 CHEMICAL CONTAINERS READILY VISIBLE IN AND ARROUND THE FACILITY.

D. OSC DIRECTED BY ERS CHIEF MASSEY TO INFORM THE STATE THAT THIS IS A 100 PERCENT FED LEAD PROJECT. ALL INFO TO BE MADE AVAILABLE, ALL ASPECTS OF CASE/CLEANUP ARE FED LEAD.

E. OSC MET WITH MSD BALTHORE STATE AND FIRE DEPARTMENT AT OBOO HOURS

E. OSC MET WITH MSD BALTIMORE STATE AND FIRE DEPARTMENT AT 0800 HOURS 5-28-87 REGARDING FUTURE PLANS. OSC REITERATED MOU POLICY AND NEED FOR EPA PARTICIPATION AFTER 48 HOURS USC ACTION. OSC RECOMMENDS CONTINUATION OF EMERGENCY RESPONSE UNDER 50 K CERCLA DELEGATION OF AUTHORITY AT THIS TIME. ALL PARTIES PRESENT CONCURRED WITH OSC DECISION AND REQUEST TO SHARE INFORMATION AMONG ALL AGENCIES.
F. OSC CONTACTED POTENTIAL RESPONSIBLE PARTIES VIA TELEHONE 5-28-87

REGARDING PRP. TAKEOVER. PRP UNABLE TO FINANCIAL ABATE THE THREAT OF FIR AND EXPLOSION PRESENTED BY THE SITE, THEREFORE, OSC ACTIVATES 50 K AT 1032 HOURS 5-28-87. ERCS ACTIVATED AT 1051 HOURS 5-28-87.

1032 HOURS 3-28-87. ERCS HETTAMED, HT 1031 HOURS 3-28-87. GC)SC NOTIFIED EPA/OPA AT 0730 HOURS 5-28-87 REGARDING SITE ACTIVITIES.

A. OSC TO MOBILIZE ERCS FOR COMPLETION OF CHEMICAL INVENTORY IN AND AROUND THE FACILITY AND FOR PROVISION OF 24 HOUR SITE SECURITY.

B. AS PER OSC: INSTRUCTION, TAT TO PREPARE SCOPE OF WORK FOR INVENTORY ACTIVITIES, SITE SAFETY PLAN, CONTINGENCY PLAN (IN ACCORDANCE WITH USCG REGIONAL AND LOCAL PLANS), 50 K FUNDING REQUEST, AN ENVIRONMENTAL SAMPLING PLAN.

C. USC TO CONTINUE WITH RESPONSE ACTIVITIES AS PLANNED, REQUEST FOR ADDITIONAL FUNDS TO FOLLOW AS NEEDED.

ROBERT CARON OSC EPA REGION III PHILADELPHIA PA

1127 EST

EPADHM PHA

To: ERD/OEPR (EPA5511)
To: B.CARON (EPA5340)
To: T.MASSEY (EPA5374)

From: T.MASSEY (EPA9374) Delivered: Subject: BALMO.PR2

Mail Id: IPM-163-870529-092480253

POLREP #2 Capitol Assay Labs Site Philtimoton Avenue Baltimore, Md ATTN: T. Massey and T. Fields

I. SITUATION (2200 hours 5/28/87)

A. OSC activates \$50K emergency funding under delegation of Authority this date at 1021 hours this date to provide site security and a complete chemical inventory at the site after PRPs contacted denied cleanup responsibility. EPA, state, ERCS and TAT perform additional site entry to determine strategy for action. PRP interest in assuming responsibility for site activities apparent to OSC. EPA Legal and EPA Enforcement by C. D. R. this date. Site activities under \$50K to continue as needed under OSC supervision.

Fri

29-May-87 10:16 EDT Sys 163"

B. Personnel on scene:
EPA-4
TAT-3
MDWMA-5
BALTIMORE HEALTH DEPT-2
ERCS-6
USCG-5
PRPS- 3

C. Weather: hot, mid 80'2

D. Costs to date: ERCS: * 6K TAT: * 4K EPA: * 1K

. E. State of Maryland WMA provides OSC A.M. Cox for duration of project.

II. ACTIONS TAKEN

A. Subsequent to EPA/USCG meeting in MSC Baltimore, EPA, TAT USCG, State, and fire department personnel on scene 1300 hours to perform additional assessment of site conditions. ERCS on site 1415 hours; accompanied EPA on entry at approx. 1500 hours. Site security arranged by 1430 hours.

11

- P. QSC contacts EPA legal counsel K. μ Rader regarding PRP intentions on site cleanup. PRP (Mechan) counsel to contact EPA by 1930 hours with decision. Site activities continue as planned junder #50K emergency funds.
- C. EPA Enforcement R. Dulcey on site 1030 hours as per OSC request.
- D. PRP representative D. Cohen (chemist Capitol Assay), B. Recker (landlord) and landlord maintenance personnel on site at 1700 hours to discuss future plans and possible assumption of cleanup by PRP. $f_{\rm c}$

10% FUTURE PLANS

- A. ERCS to begin inventory of building contents 5/29/87.
- H. ERCS/TAT to collect environemtnal mamples 5/29/87.
- C. Site security to continue as funding available.
- Emergency removal activities to continue as circumstances require.
 - E. PRP mesting scheduled for 1530 hours 5/29/87.
- F. Press conference scheduled for 1400 hours 5/29/87. QPA Sinclair/state Feldman ato be on scene.

Robert E. Caron, OSC EPA Region III Philadelphia, PA

```
TEX II RECV
                COMMERTED
                             25-May-87 C 107 05
EPACHM PHA
WU INFOMASTER
                4-0024128150-001 05/30/87
ICS IPMMTZZ CSP
  794820222 DGM TDMT UG CHERRY HILL 289
                                            05-30 0804A EST
1 mX 7106700716 EPACHM PHA
EMERGENCY RESPONSE
4218 EPA PHA
POLREP #3
CAPITOL ASSAY LABS SITE
WHITTINGTON AVENUE
BALTIMORE, MD
ATTN: TOM MASSEY AND TIM FIELDS
I. SITUATION (1800 HOURS 5/29/87)
   A. PERSONNEL ON SCENE: EPA/OSC-1. EPA/OPA-1. EPA/ENFORCEMENT-1.
MDWMA-4, USCG-4, TAT-3, BALTIMORE CITY FIRE DEPARTMENT-4. ERCS-10
   B. ESTIMATED COSTS TO DATE: EPA-$2000, TAT-$5800, ERCS-$10,000.
HQ-$4000
   C. SITE INVENTORY AND ENVIRONMENTAL SAMPLING BEGINS: THIS DATE.
TEMPERATURES IN THE MID-909 SLOWS THE ASSESSMENT PROCESS.
 L. MDWMA OSC (COX) CONTINUES TO PROVIDE ON SITE SUPPORT.
   E. USCG PROVIDES COMMAND POST FOR SITE ACTIVITIES.
   F. PRP CONTINUES TO BE UNCOOPERATIVE.
   G. 24 HOUR SITE SECURITY CONTINUES.
   H. ERCS HAVING DIFFICULTY MEETING OSC STAFF REQUIREMENTS. OSC
DIRECTED RESPONSE MANAGER TO CORRECT IMMEDIATELY.
ACTIONS TAKEN:
  A. 0800 HOURS-DSC (CARON), TAT, AND ERCS ON SCENE TO SEGIN CHEMICAL
INVENTORY (BUILDING A).
   B. TATS PERFORMS ENVIRONMENTAL SAMPLING (SOIL AND MATER) OF DRAINAGE
AREA BEHIND THE FACILITY. ANALYSIS (ERCS LAB) TO INCLUDE: PRIORITY
POLLUTANT METALS, VOLATILE ORGANICS, BASE NEUTRALS, AND CYANIDE.
   C. AIR MONITORING AND ABBESSMENT OF OFFICE CONDUCTED.
   D. 1400 HOURS-1445 HOURS PRESS CONFERENCE HELD ON SITE. PERSONNEL
ATTENDING INCLUDE: EPA/OPA (SINCLAIR), EPA/OSC (CARON), MDOEP
(FELDMANN), MOWMA, PRP ATTORNEY, AND THE SUN.
   E. 1530 HOURS EPA, USCS, AND MONMA MEET WITH PRA TO DISCUSS CLEANUP
OPTIONS AND CONTINUE NEGOTIATIONS FOR POSSIBLE PRP-TAKEOVER OF CLEANUP.
   F. 1545 HOURS-1617 HOURS, TV-CHANNELS 2 AND 13 ONL SCENE. -INTERVIEW
WITH EPA/OPA AND MODEP.
   G. 1706 HOURS BUILDING A CLOSED AND SECURED.
   H. 1815 HOURS PRP CONTRACTOR (JOL INDUSTRIES) PERFORMS VISUAL SITE
ASSESSMENT.
III. FUTURE PLANSE
   A. CHEMICAL INVENTORY AND SITE SECURITY TO CONTINUE (ESTIMATED 2-3
```

DAYS FOR COMPLETION)

B. UPON INVENTORY COMPLETION SCOPE OF WORK TO BE DRAFTED. C. OSC AWAITING: RESULTS OF ENFORCEMENT EFFORTS WITH PRP NEGOTIATIONS. RUBERT E CARON, OSC

U.S. EPA, REGION III PHILADELPHIA, PA

0807 EST

1

EPACHM PHA

ERD/OERR (EPA5511) To:

To: T. MASSEY (EPA9374)

F. HENDERSON Tos (EPX2992)

T. MASSEY (EPA9374) Delivered: Fri 5-June-97 14:47 EDT Sys 163 Froms POLREPS 4,5 & 6 CAPITOL ASSAY LASS SITE Bubject:

IPM-163-870605-133180385 Mail Ide

CAPITOL ASSAY LABS SITE WHITTINTON AVE

POLREP #4

BALTIMORE, MD

ATTN: TOM MASSEY AND TIM FIELDS:

- SITUATION (1800 HRS., 5/30/87):
 - PERSONNEL ON-SCENE: EPA/OSC-1 EPA/OPA-1

MD WMA-1 TAT-3

ERCS-9

ESTIMATED COSTS TO DATE: EPA-\$2,500 TAT-\$7,600 ERCS-\$16,000

OF BUILDING A CHEMICAL INVENTORY CONTINUES. TEMPERATURES IN THE HIGH 90'S SLOWS LEVEL "B" OPERATIONS.

HG-\$8,000 .

- MD WMA OSC (COX) CONTINUES TO PROVIDE ON-SITE SUPPORT. D.
- 24 HR SITE SECURITY CONTINUES.
- OBC CLARK ACTING FOR OBC CARON THIS DATE.

ACTIONS TAKEN II.

- A. ERCS CONTINUED THE INVENTORY OF CHEMICALS/CONTAINERS IN BUILDING A. A TOTAL OF 321 CONTAINERS WERE LOGGED AND LABELLED THIS DATE. HOWEVER, BUILDING A INVENTORY IS NOT COMPLETED.
- B. OPEN MERCURY CONTAINER (5 GAL IN BLDG A) PLACE IN OVERPACK.
- C. TV CHANNELS 13 AND 11 ON-SCENE TO INTERVIEW WITH OPA SINCLAIR AND OSC CLARK.
- 'D. BECAUSE COSTS (ANALYTICAL INCLUDED) ARE APPROACHING THE SOK CEILING, OSC REQUESTS THAT ALL SITE OPERATIONS BE SHUT DOWN AT 1600 HRS THIS DATE. BUILDING A WAS CLOSED. AND SECURED. KEYS TO ALL LOCKS WERE GIVEN TO MD WMA COX.
- E. USCS RETRIEVED COMMAND POST.

- F. BALTIMORE CITY FIRE DEPARTMENT RETRIEVED FIRE HOSE.
- G. ALL PERSONNEL OFF SITE AT 1730 HRB.

III. FUTURE PLANS:

- A. TAT AND ERCS TO DEMOSE 5/31/87.
- B, OSC PLANS TO REQUET ADDITIONAL FUNDS IN ORDER TO COMPLETE THE ASSESSMENT OF BUILDINGS A AND B.
- C. TAT TO DELIVER ENVIRONMENTAL SAMPLES TO ERCS LAB (READING, PA) ON 5/31/87. OSC REQUESTS VERBAL RESULTS IN 3 DAYS (6/3/87).
- D. SITE SECURITY TO CONTINUE UNTIL FURTHER NOTICE.

ROBERT E. CARON, OSC LISA CLARK, OSC U.S. EPA, REGION 111 PHILADELPHIA, PA To: ERD/DERR (EPA5511)

To: T. MASSEY (EPA9374)
To: F. HENDERBON (EPX2992)

From: T.MASSEY (EPA9374) Delivered: Fri 5-June-87 14:55 EDT Sys 163

Subject: CAPITOL ASSAY LASS SITE POLREPS Mail Id: IPM-163-870605-134320317

POLREP #5

CAPITOL ASSAY LARS SITE WHITTINTON AVE

BALTIMORE, MD

ATTN: TOM MASSEY AND TIM FIELDS:

- . SITUATION (1500 HRS., G/3/87):
 - A. OSC CURRENTLY AWAITING APPROVAL ON ADDITIONAL FUNDING REQUEST SO THAT SITE ASSESSMENT CAN BE COMPLETED AND CLEANUP ACTION CAN BE STARTED.
 - B. ESTIMATED COSTS TO DATE: EPA-\$3,000 TAT-\$11,000

ERCS-\$16,000

HO-#8,000

- C. RESPONSIBLE PARTY HIRED CONTRACTOR FOR GUOTE ON CLEANUP.

 24 HR. SITE SECURITY MAINTAINED WHILE ORIGINAL & 50K FUNDS REMAIN
- II. ACTIONS TAKEN:
 - A. TAT DELIVERED ENVIRONMENTAL SAMPLES TO LAB FOR ANALYSIS 6/3/87.
 - B. ADDITIONAL FUNDING REQUEST PREPARED AND THROUGH THE CHAIN OF CONCURRENCE 6/2/87.
 C. ENFORCEMENT STATEMENT CURRENTLY BEING PREPARED FOR
 - ADDITIONAL FUNDING REQUEST. D. EPA OPA IN CONTACT WITH TIM MURPHY, MD CONGRESSMAN TO
- III. FUTURE PLANS:
 - R. OSC CLARK, TAT AND EPA ENFORCEMENT TO BE ON SCENE 6/4.
 B. RESPONSIBLE PARTY TO HAVE CONTRACTOR ON SITE TO PREPARE
 - RESPONSIBLE PARTY TO HAVE CONTRACTOR ON SITE TO PREPARI QUOTE TO CLEANUP SITE.
 SITE SECURITY TO CONTINUE UNTIL FURTHER NOTICE.
 - C. SITE SECURITY TO CONTINUE UNTIL FURTHER NOT D. PUBLIC MEETING SCHEDULED FOR JUNE 10, 1987.

INFORM HIM OF FUTURE PUBLIC MEETING.

ROBERT E. CARON, USC LISA CLARK, OSC U.S. EPA, REGION III PHILADELPHIA, PA 1;

Tos ERD/DERR (EPA5511) Tot T. MASSEY (EPA9374) F. HENDERSON (EPX2992) Tos Fromi T. MASSEY (EPA9374) Delivered: Fri 5-June-87 14:57 EDT Sys 163 Bubject: POLREP 6

H

Mail Id: IPM-163-870505-134680066

POLREP #6

CAPITOL ASSAY LABS SITE WHITTINTON AVE BALTIMORE, MD

ATTN: TOM MABSEY AND TIM FIELDS:

I. SITUATION (1700 HRB., 6/4/87):

EPA-2, TAT-2, MDOEP-2, A. PERSONNEL ON SCENE: PRP CONTRACTOR-3, VERSAR-2.

₽. ADDITIONAL FUNDING REQUEST APPROVED 6/4.

c. ESTIMATED COSTS TO DATE: EPA-#3, 500 TAT-\$12,000

ERC8-\$16.000 HQ-#8,000

SITE SECURITY MAINTAINED WHILE ORIGINAL & SOK D. 24 HR. FUNDS REMAIN

ENFORCEMENT UNABLE TO RETRIEVE ANY INFORMATION ABOUT RP WITHOUT A SEARCH WARRANT. CRIMINAL INVESTIGATION CURRENTLY IN PROGRESS.

II. ACTIONS TAKEN:

DSC CLARK, TAT AND EPA ENFORCEMENT (DULCEY) ON SCENE THIS A. DATE. в. TAT MADE LEVEL B ENTRY WITH RP CONTRACTOR (J&L IND.). J&L

ON SCENE TO PREPARE PRICE QUOTE FOR RP., FOR

ENFORCEMENT ON SCENE TO GATHER INFORMATION ABOUT COMPANY OPERATION/PRACTICES.

III. FUTURE PLANS:

A. AWAITING RESULTS ON ENVIRONMENTAL SAMPLES TAKEN 5/30.

₽. SITE SECURITY TO CONTINUE UNTIL FURTHER NOTICE.

PUBLIC MEETING SCHEDULED FOR JUNE 10, 1987. EPA AWAITING DECISION FROM RP TO TAKE OVER CLEANUP. c.

1

ROBERT E. CARON, OSC LISA CLARK, OSC. U.S. EPA, REGION III PHILADELPHIA, PA

To: ERD/DERR (EPASS11)
To: T.MASSEY (EPAS374)
To: T.MASSEY (EPAS374) Delivered: Thu 16-July-87-15:06 EDT Sys 163

Joubject: polrep 7 and final : CAPITOL ABBAY LAB SITE 🛖 Mail Id: IPM-163-870716-135950539

POLRED #7 AND FINAL

CAPITOL ASSAY LABS WHITTINGTON AVE. SALTIMORE CITY. MD

ALTH: TOM MAGSEY AND TIM FIELDS

- I. SITUATION: (1700 HRS. 7/8/87)
 - A. EPA PROGRAM ELEMENTS SUCCESSFULL IN OBTAINING A COMMITTMENT FROM THE RESPONSIBLE PARTY TO TAKE OVER THE CLEANUP.
 - RESULTS FROM ENVIRONMENTAL SAMPLES COLLECTED BY TAT OUTSIDE THE LAB SHOWED NO SIGNIFICANT SIGNS, OF CONTAMINATION.
 - C. ERCS CONTROCTOR EXCREDED * 30 K BUDGET BY PROVIDING SITE SECURITY THROUGH 6/87/87 UNTIL THE RP AGREED TO TAKE RESPONSIBILITY. ADDITIONAL P.R. OF *1 K WHITTEN TO COVER ERCS COST. FUNDS SHIFTED FROM INITIAL *50 K FROM TAT AND EPA BUDGET.
- II. ACTIONS TAKEN
 - A. PUBLIC MEETING HELD 1930 HRS 6/10/87 AT THE MORRELL PARK REC. CENTER. PUBLIC SHOWED GRATITUDE FOR EPA'S PRESENCE AND CONCERN.
 - B. WIPE SAMPLES COLLECTED BY TAT FROM THE FILE BOXES
 OBTAINED FROM CAPITOL ASSAY LAB SHOWED NO SIGNIFICANT
 SIGNS OF CONTAMINATION AFTER REVIEW FROM CDC.
- III. FUTURE PLANS
 - A. RP CLEANUP ONGOING UNDER DIRECTION OF EPA ENFORCEMENT, RICH DULCEY.

ROBERT E. CARON. OBC LISA M. CLARK, OBC US EPA REGION'III ...PHILA.. PA SPILLSEFA WSH SPECIAL BULLETIN

CAPITOL ASSAY LARG WHITTINGTON AVENUE BALTIMORE CITY. MD

ATTN: TOM MASSEY, TIM FIELDS AND DICK MUELLER

- I. SITUATION (1630 HRS. 08/05/87)
 - A. ERCS CONTRACTOR EXCEEDED \$31K BUDGET BY PROVIDING ADDITIONAL SITE SECURITY THROUGH 06/27/87 WHEN THE RP AGREED TO TAKE SITE RESPONSIBILITY. ERCS CONTRACTOR ALSO INCURRED COSTS FOR A LOCKSMITH NECESSITATED BY APPARENT VANDALISM AT THE
 - B. FAS (MCGOWAN) SPOKE WITH MARSHA ROBINSON (O.H. MATERIALS) AND MARY ROGERS (HEADQUARTERS-PROCUREMENT) CONCERNING COST OVERRUN.
 - C. MARY ROGERS INDICATED THAT THERE WAS A PROBLEM WITH THE SITE CEILING SINCE HER RECORDS INDICATED AN ERCS CEILING OF \$51K AND A DELIVERY ORDER FOR \$30K.
 - D. FAS (MCGOWAN) INDICATED THAT THERE WAS AN ERROR IN THE ORIGINAL PROCUREMENT REQUEST (WHICH WAS WRITTEN FOR \$50K). AN ADDITIONAL PROCUREMENT REQUEST HAD BEEN WRITTEN FOR \$1K BRINGING THE SITE CEILING TO \$51K AS INDICATED BY MARY ROGERS.
 - E. FAS (MCGOWAN) INDICATED THAT THE ORIGINAL PROCUREMENT REQUEST SHOULD HAVE BEEN WRITTEN FOR \$30K. THAT PROCUREMENT REQUEST, ALONG WITH THE ADDITIONAL \$1K PROCUREMENT REQUEST, BROUGHT THE ERCS CEILING TO \$31K.

II. ACTIONS TAKEN

- A. FAS (MCGOWAN) PREPARED A PROCUREMEN'S REQUEST AND MEMO OF EXPLANATION TO HEADQUARTERS TO DECREASE THE ERCS CEILING BY \$20K FROM \$51K TO \$31K.
- B. FAS (MCGOWAN) CONTACTED MARSHA ROBINSON (O.H. MATÉRIALS) TO OBTAIN AN ACCURATE FINAL COST FOR THE SITE. IN ORDER TO FACILITATE THIS REQUEST, ROBINSON HAD AN INTERNAL AUDIT PERFORMED ON THE SITE RECORDS.
- C. FAS (MCGOWAN) WAS NOTIFIED BY ROBINSON (O.H. MATERIALS) THAT, BARRING ANY UNFORESEEN COSTS, THE TOTAL COSTS FOR THE SITE WERE \$32,288.41.
- D. FAS (MCGOWAN) DISCUSSED THE SITUATION WITH OSC (CLARK) AND MADE A RECOMMENDATION THAT AN INCREASE OF \$2K BE MADE TO THE ERCS CEILING. THIS WOULD BRING THE CEILING TO \$3K. THIS WOULD ALLOW FOR ANY INCIDENTAL INVOICES NOT YET SUBMITTED TO O.H. MATERIALS.
- E. OSC (CLARK) AGREED AND THE ADDITIONAL PROCUREMENT REQUEST FOR *2K WAS PROCESSED.
- F. FAS (MCGOWAN) INFORMED ROBINSON (D.H. MATERIALS) AND ROGERS (HEADQUARTERS-PROCUREMENT) THAT THE ADDITIONAL \$2K WAS FORTH-COMING.

III. FUTURE PLANS

A. FAS (MCGOWAN) TO RECEIVE ADDITIONAL 1900.55'S FOR SITE SECURITY AND LOCKSMITH SERVICES.

ROBERT CARON, OSC LISA M. CLARK, OSC DONNA M. MCGOWAN, FAS EPA - REGION III PHILADELPHIA, PA

DISCONNECTED 07-Aug-87 12:17 12

To: ERD/GERR (EPA5511) To: T. MASSEY (EPA9374)

From: B.CARON (EPA9340) Delivered: Thu 3-Sep-87 11:20 EDT Sys 163 (32)

MUDJect: CAP ASSAY POLREP

Mail Id: IPM-163-870903-102110235

CAPITAL ASSAY LABS WHITTINGTON AVE.

BALTIMORE, MD.

ATTN: TOM MASSEY AND TIM FIELDS,

SPECIAL BULLETIN-PROJECT STATUS

SITUATION (1200 HRS., 9/1/87)

PROGRAM ELEMENTS SUCCESSFUL IN OBTAINING RP TAKEOVER OF CLEANUP.

RP CLEANUP ONGOING UNDER CERCLA ENFORCEMENT. NOW LEAD. 9,

OSC CANNOT DETERMINE OFFICIAL SITE CLOSUKE DATE AS RP CLEANUP IS ONGOING AND RP IS EXPRESSING PROBLEMS FINANCIALLY WHICH MAY RESULT IN THE NEED FOR OSC TAKEOVER. PROJECT 10 REMAIN OPEN UNTIL FIRM COMMITMENTS FROM RP ARE SECURED.

II. FUTURE PLANS

OSC TO MONITOR CLEANUP VIA ENFORCEMENT OFFICER.

OSC TO ISSUE FINAL POLREP WHEN ACTION IS COMPLETE. в.

OSC REPORT TO BE DRAFTED AND FINALIZED AND SUBMITTED AS NCP DICTATES.

ROBERT E. CARON, OSC USEPA-III) PHILADELPHIA, PA.

CAPITAL ASSAY LASS WHITTINGTON AVENUE BALTIMORE CITY, MD

MÁTTN: TIM FIELDB AND MIKE ZICKLER

SPECIAL BULLETIN - PROJECT STATUS

- I. SITUATION (1200 HOURS, FRIDAY, OCTOBER 30, 1987)
- A. EPA PROGRAM ELEMENTS BUCCESSFUL IN OBTAINING RP TAKEOVER OF CLEANUP.
- B. RP CLEANUP ONGOING UNDER DIRECTION OF EPA ENFORCEMENT (RICHDUCLEY).
- C. OBC CANNOT DETERMINE OFFICIAL SITE CLOSURE DATE AT THIS TIME AS RP CLEANUP IS ONGOING. PROJECT TO REMAIN OPEN AS CONTINGENCY SHOULD FURTHER EPA ACTION BE NECESBARY, IE. SHOULD RP CLEANUP BE DETERMINED TO BE UNSATISFACTORY.

II. FUTURE PLANS

- A. OSC TO MONITOR RP CLEANUP PROGRESS VIA EPA ENFORCEMENT.
- B. OBC TO ISSUE FINAL POLREP WHEN CLEANUP IS DETERMINED TO COMPLETE AND SATISFACTORY.
- C. OSC REPORT TO BE DRAFTED, FINALIZED AND SUBMITTED IN ACCORDANCE WITH NCP REQUIREMENTS UPON OFFICIAL PROJECT CLOSURE AS DETERMINED BY THE OSC.

ROBERT E. CARON, OSC LISA M. CLARK, OSC EPA REGION III PHILA., PA

THE SUN Maryland



Employees working under contract to the EPA prepare to enter Capital Assay Laboratories.

100054

Federal officials mobilize cleanup of leaking acid

Emergency workers enter warehouse

By Liz Bowie

Federal officials began yesterday an emergency cleanup of several hundred leaking drums of chemicals and cylinders of dangerous gases found Tuesday improperly stored in a warehouse at a Southwest Balti-


more industrial park,
State and federal officials said they mobilized federal chemical cleanup workers because of the risk that the stored acids might mix and cause a fire or toxic cloud. They also said they did not believe officials of the financially ailing business were adequately supervising the chemi-

The closest residential area is about a quarter-mile away in Morrell

Company officials contended the federal environmental officials locked them off the grounds and said the company would like to assist in

the company would like to assist in the cleanup effort.
Inside the 10,000-square-foot Capital Assay Laboratories Ltd. building are several hundred drums of chemicals, including nitric, sulfu-ric and hydrochloric acids, Some of the drums are new and others are the drums are new and others are badly corroded, said Bob Caron, who supervises cleanups at sites the U.S. Environmental Protection Agency designates as emergencies covered by its Superfund.

Chlorine and sulfur dioxide gases



also were found at the precious metal reclaiming company in one end of a long warehouse in the Whittington Business Center not far from the intersection of Patapsco Avenue and Washington Boulevard.

. The acids and gases, which are highly corrosive and can cause severe respiratory problems if the fumes are inhaled, were used in a chemical process that extracted pre-cious metals, such as gold and silver.

from scrap,

Most of the chemicals were found inside the building, but several drums were left outside behind the

See SUPERFUND, 8A, Col, 2

Emergency workers sent to clean up leaking acid

SUPERFUND, from 8A

Yesterday EPA workers were placing leaking drums in large protective containers and separating chemicals that could be hazardous in combination. After an inventory of all the chemicals on the site, the EPA will decide how to get rid of them, Mr. Caron said. Until then, a 24-hour guard will monitor the property.

erty.

While state and EPA officials believed the contents of the building, if
left unattended, presented a risk to
public health, Mr. Caron said he
does not believe the chemicals contaminated ground water or soil.

The site was discovered by accident when a representative from the Baltimore County sheriff's office and a collection agency went to Capital Assay Laboratories to look for anything of value that would satisfy a creditor's claim agains; the company. They opened the door with a crowbar, state officials said.

Upon finding the chemicals and gas cylinders, the sheriff's department alerted the Maryland Office of Environmental Programs. After visiting the site that afternoon, state health department officials then

called the EPA for emergency manpower in cleaning up the building.

The business has not been operating normally for several weeks, and an employee told state officials he had not been paid for eight or nine weeks, said Ray Feldmann, an OEP spokesman.

But an attorney for Capital Assay Laboratories said the company was operating until Tuesday, when employees came to work and discovered they could not get in because someone had padlocked the door.

Company President John P. Meighan of Baltimore County declined to comment on the situation. But his attorney, David S. Pearl, and company officials felt the EPA "came

in like gang busters."
"It's a normal operating business
you find in an industrial park," Mr.

He contends that EPA locked out the owners of the company and refused to allow them to take the company's financial records from the building.

The EPA will ask Capital Assay's owners to reimburse the government for the \$50,000 it has estimated the cleanup will cost, spokeswoman Nanci Sinciair said,